## 12, 13 and AMM Series Multimedia Head Units w/ jLink3 Cable (Black)

# VM9312 / VM9312HD / VM9313 / VM9412 / VM9413 / VM9512 / AMM10N / VM9512HD / VM9022 / AMM12N / VM9022HD / VM9022HDN / VM9423

	iPod Feature					
	Audio Playback	Video Playback	Audio Control	Charging		
iPod Model						
iPod Nano	Yes	N/A	Yes	Yes		
iPod Nano (2nd Gen)	Yes	N/A	Yes	Yes		
iPod Nano (3rd Gen)	Yes	Yes	Yes	Yes		
iPod Nano (4th Gen)	Yes	Yes	Yes	Yes		
iPod Nano (5th Gen)	Yes	Yes	Yes	Yes		
iPod (4th Gen)	Yes	N/A	Yes	Yes		
iPod (5th Gen)	Yes	Yes	Yes	Yes		
iPod Classic	Yes	Yes	Yes	Yes		
iPod Touch	Yes	Yes	Yes	Yes		
iPod Touch (2nd Gen)	Yes	Yes	Yes	Yes		
iPod Touch (3rd Gen)	Yes	Yes	Yes	Yes		
iPhone	Yes	Yes	Yes	Yes		
iPhone (2nd Gen) / iPhone 3G / 3GS	Yes	Yes	Yes	Yes		

#### Notes:

1. 12, 13 and AMM Series head units will require a software update to be compatible with the jLink3 if the head unit came with the original jLink cable. If the head unit has already been updated for jLink2 compatibility, then no further update is necessary for jLink3

## 13 Series Multimedia Head Units w/ jLink3 Cable (Black)

### VM8013 / VM8013HD / VM8023HD

	iPod Feature					
	Audio Playback	Video Playback	Audio Control	Charging		
iPod Model				•		
iPod Nano	Yes	N/A	Yes	Yes		
iPod Nano (2nd Gen)	Yes	N/A	Yes	Yes		
iPod Nano (3rd Gen)	Yes	Yes	Yes	Yes		
iPod Nano (4th Gen)	Yes	Yes	Yes	Yes		
iPod Nano (5th Gen)	Yes	Yes	Yes	Yes		
iPod (4th Gen)	Yes	N/A	Yes	Yes		
iPod (5th Gen)	Yes	Yes	Yes	Yes		
iPod Classic	Yes	Yes	Yes	Yes		
iPod Touch	Yes	Yes	Yes	Yes		
iPod Touch (2nd Gen)	Yes	Yes	Yes	Yes		
iPod Touch (3rd Gen)	Yes	Yes	Yes	Yes		
iPhone	Yes	Yes	Yes	Yes		
iPhone (2nd Gen) / iPhone 3G / 3GS	Yes	Yes	Yes	Yes		

#### Notes:

- 1. 13 Series head units will require a software update to be compatible with the jLink3 if the head unit came with the original (White) jLink cable. (Early VM8013's came with the original (White) jLink cable) If the head unit has already been updated for
- 2. When an iPod is connected via **jLink2 / jLink3**, you must manually select the iPod source. In addition, when reconnecting the iPod, if it was disconnected (and the jLink2 / jLink3 is still plugged into the head unit) you must rotate throught the sources